


Digital multimeter connections



Resistance, voltage, current, capacitance and continuity are measured by selecting the proper range and sockets.